

PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN PSI	FT. LBS.	N-m	10MD
1000	1050	1424	
1200	1282	1742	
1400	1490	2020	
1600	1710	2318	
1800	1935	2624	
2000	2140	2901	
2200	2380	3227	
2400	2605	3532	
2600	2810	3810	
2800	3055	4142	
3000	3265	4426	
3200	3510	4759	
3400	3725	5050	
3600	3930	5328	
3800	4145	5620	
4000	4380	5938	
4200	4585	6216	
4400	4810	6521	
4600	5035	6827	
4800	5285	7165	
5000	5510	7470	
5200	5735	7776	
5400	5950	8067	
5600	6190	8393	
5800	6410	8691	
6000	6630	8989	
6200	6845	9281	
6400	7060	9573	
6600	7300	9897	
6800	7520	10196	
7000	7755	10514	
7200	7980	10819	
7400	8200	11118	
7600	8425	11423	
7800	8645	11721	®
8000	8880	12040	
8200	9090	12325	
8400	9315	12629	
8600	9545	12941	
8800	9765	13240	
9000	10000	13558	
9200	10230	13870	
9400	10460	14182	
9600	10670	14467	
9800	10900	14778	
10000	11206	15193	