

# LOW/XLCT-4 Torque Chart Low Profile



Pump Pressure in PSI	Ft. Lbs. Torque	NM of Torque	Pump Pressure in BAR
1500	632	857	103
1600	705	956	110
1800	778	1055	124
2000	850	1152	138
2200	935	1268	152
2400	1020	1383	166
2600	1105	1498	179
2800	1190	1613	193
3000	1273	1726	207
3200	1358	1841	221
3400	1443	1956	234
3600	1528	2072	248
3800	1613	2187	262
4000	1698	2302	276
4200	1786	2421	290
4400	1874	2541	303
4600	1962	2660	317
4800	2050	2779	331
5000	2137	2897	345
5200	2223	3014	359
5400	2309	3131	372
5600	2395	3247	386
5800	2481	3364	400
6000	2565	3478	414
6200	2654	3598	428
6400	2743	3719	441
6600	2832	3840	455
6800	2921	3960	469
7000	3008	4078	483
7200	3094	4195	497
7400	3180	4312	510
7600	3266	4428	524
7800	3352	4545	538
8000	3436	4659	552
8200	3524	4778	566
8400	3612	4897	579
8600	3700	5017	593
8800	3788	5136	607
9000	3877	5257	621
9200	3961	5370	634
9400	4045	5484	648
9600	4129	5598	662
9800	4213	5712	676
10000	4300	5830	690

Tool Owner:

Serial Number:

Calibrated By:

Due Date:

Accuracy of Tool to Chart Within 3%:

Please call us at:  
**+27 32 9470577**

Manufacturer: Wren  
 Model Number: LOW/XLCT-4  
 Max Pressure 10,000 PSI