

IBT/MXTA-3 Torque Chart 1" Drive



Pump Pressure in PSI	Ft. Lbs. Torque	NM of Torque	Pump Pressure in BAR
1500	485	658	103
1600	517	701	110
1800	581	788	124
2000	646	876	138
2200	711	964	152
2400	775	1051	166
2600	840	1139	179
2800	904	1226	193
3000	969	1314	207
3200	1034	1402	221
3400	1098	1489	234
3600	1163	1577	248
3800	1227	1664	262
4000	1292	1752	276
4200	1357	1840	290
4400	1421	1927	303
4600	1486	2015	317
4800	1550	2102	331
5000	1615	2190	345
5200	1680	2278	359
5400	1744	2365	372
5600	1809	2453	386
5800	1873	2539	400
6000	1938	2628	414
6200	2003	2716	428
6400	2067	2802	441
6600	2132	2891	455
6800	2196	2977	469
7000	2261	3066	483
7200	2326	3154	497
7400	2390	3240	510
7600	2455	3329	524
7800	2519	3415	538
8000	2584	3503	552
8200	2649	3592	566
8400	2713	3678	579
8600	2778	3766	593
8800	2842	3853	607
9000	2907	3941	621
9200	2972	4029	634
9400	3036	4116	648
9600	3101	4204	662
9800	3165	4291	676
10000	3230	4379	690

Tool Owner:

Serial Number:

Calibrated By:

Due Date:

Accuracy of Tool to Chart Within 3%:

Please call us at:
+27 32 9470577

Manufacturer: Wren
 Model Number: 3 IBT/MXTA
 Max Pressure 10,000 PSI