

# LOW/XLCT-14 Torque Chart Low Profile



Pump Pressure in PSI	Ft. Lbs. Torque	NM of Torque	Pump Pressure in BAR
1500	1775	2407	103
1600	1899	2575	110
1800	2144	2907	124
2000	2390	3240	138
2200	2637	3575	152
2400	2883	3909	166
2600	3130	4244	179
2800	3376	4577	193
3000	3623	4912	207
3200	3873	5251	221
3400	4124	5591	234
3600	4374	5930	248
3800	4625	6271	262
4000	4876	6611	276
4200	5130	6955	290
4400	5383	7298	303
4600	5638	7644	317
4800	5892	7988	331
5000	6146	8333	345
5200	6405	8684	359
5400	6665	9037	372
5600	6925	9389	386
5800	7185	9742	400
6000	7445	10094	414
6200	7700	10440	428
6400	7955	10786	441
6600	8211	11133	455
6800	8466	11478	469
7000	8721	11824	483
7200	8977	12171	497
7400	9233	12518	510
7600	9488	12864	524
7800	9744	13211	538
8000	10000	13558	552
8200	10255	13904	566
8400	10509	14248	579
8600	10764	14594	593
8800	11018	14938	607
9000	11273	15284	621
9200	11517	15615	634
9400	11760	15944	648
9600	12003	16274	662
9800	12247	16605	676
10000	12500	16948	690

Tool Owner:

Serial Number:

Calibrated By:

Due Date:

Accuracy of Tool to Chart Within 3%:

Please call us at:  
**+27 32 9470577**

Manufacturer: Wren  
 Model Number: LOW/XLCT-14  
 Max Pressure 10,000 PSI