

# LOW/XLCT-2 Torque Chart Low Profile



Pump Pressure in PSI	Ft. Lbs. Torque	NM of Torque	Pump Pressure in BAR
1500	220	298	103
1600	235	319	110
1800	267	362	124
2000	298	404	138
2200	330	447	152
2400	361	489	166
2600	393	533	179
2800	424	575	193
3000	456	618	207
3200	488	662	221
3400	520	705	234
3600	552	748	248
3800	585	793	262
4000	617	837	276
4200	648	879	290
4400	680	922	303
4600	711	964	317
4800	743	1007	331
5000	774	1049	345
5200	807	1094	359
5400	840	1139	372
5600	874	1185	386
5800	907	1230	400
6000	940	1274	414
6200	972	1318	428
6400	1004	1361	441
6600	1036	1405	455
6800	1068	1448	469
7000	1100	1491	483
7200	1133	1536	497
7400	1166	1581	510
7600	1199	1626	524
7800	1232	1670	538
8000	1265	1715	552
8200	1298	1760	566
8400	1330	1803	579
8600	1362	1847	593
8800	1395	1891	607
9000	1427	1935	621
9200	1459	1978	634
9400	1489	2019	648
9600	1521	2062	662
9800	1552	2104	676
10000	1590	2156	690

Tool Owner:

Serial Number:

Calibrated By:

Due Date:

Accuracy of Tool to Chart Within 3%:

Please call us at:  
**+27 32 9470577**

Manufacturer: Wren  
Model Number: LOW/XLCT-2  
Max Pressure 10,000 PSI