

LOW/XLCT-30 Torque Chart Low Profile



Pump Pressure in PSI	Ft. Lbs. Torque	NM of Torque	Pump Pressure in BAR
1500	3839	5205	103
1600	4123	5590	110
1800	4693	6363	124
2000	5262	7134	138
2200	5845	7925	152
2400	6428	8715	166
2600	7011	9506	179
2800	7594	10296	193
3000	8177	11087	207
3200	8757	11873	221
3400	9337	12659	234
3600	9916	13444	248
3800	10496	14231	262
4000	11076	15017	276
4200	11666	15817	290
4400	12255	16616	303
4600	12845	17415	317
4800	13434	18214	331
5000	14024	19014	345
5200	14618	19819	359
5400	15212	20625	372
5600	15806	21430	386
5800	16400	22235	400
6000	16994	23041	414
6200	17591	23850	428
6400	18187	24658	441
6600	18784	25468	455
6800	19380	26276	469
7000	19977	27085	483
7200	20569	27888	497
7400	21161	28690	510
7600	21752	29492	524
7800	22344	30294	538
8000	22936	31097	552
8200	23528	31900	566
8400	24120	32702	579
8600	24712	33505	593
8800	25304	34308	607
9000	25896	35110	621
9200	26489	35914	634
9400	27082	36718	648
9600	27675	37522	662
9800	28268	38326	676
10000	28861	39130	690

Tool Owner:

Serial Number:

Calibrated By:

Due Date:

Accuracy of Tool to Chart Within 3%:

Please call us at:
+27 32 9470577

Manufacturer: Wren
Model Number: LOW/XLCT-30
Max Pressure 10,000 PSI