

LOW/XLCT-8 Torque Chart Low Profile



Pump Pressure in PSI	Ft. Lbs. Torque	NM of Torque	Pump Pressure in BAR
1500	1037	1406	103
1600	1110	1505	110
1800	1257	1704	124
2000	1403	1902	138
2200	1547	2097	152
2400	1690	2291	166
2600	1833	2485	179
2800	1977	2680	193
3000	2120	2874	207
3200	2265	3071	221
3400	2410	3268	234
3600	2555	3464	248
3800	2700	3661	262
4000	2852	3867	276
4200	2991	4055	290
4400	3137	4253	303
4600	3284	4453	317
4800	3430	4650	331
5000	3576	4848	345
5200	3723	5048	359
5400	3870	5247	372
5600	4018	5448	386
5800	4165	5647	400
6000	4312	5846	414
6200	4465	6054	428
6400	4619	6263	441
6600	4773	6471	455
6800	4926	6679	469
7000	5080	6888	483
7200	5223	7081	497
7400	5367	7277	510
7600	5510	7471	524
7800	5654	7666	538
8000	5723	7759	552
8200	5954	8073	566
8400	6111	8285	579
8600	6267	8497	593
8800	6424	8710	607
9000	6581	8923	621
9200	6730	9125	634
9400	6880	9328	648
9600	7029	9530	662
9800	7178	9732	676
10000	7320	9925	690

Tool Owner:

Serial Number:

Calibrated By:

Due Date:

Accuracy of Tool to Chart Within 3%:

Please call us at:
+27 32 9470577

Manufacturer: Wren
Model Number: LOW 8
Max Pressure 10,000 PSI